



To: DW<sup>®</sup> customers  
Date: April 4, 2019  
Re: DW<sup>®</sup> Spot<sup>™</sup> monitoring modules  
firmware update

## DW<sup>®</sup> Spot<sup>™</sup> monitoring module firmware update

**Applicable models:** DW<sup>®</sup> Spot<sup>™</sup> monitoring modules  
**New firmware version:** 1.3.5.2  
**Previous firmware version:** 1.3.4.5  
**Release date:** 04/01/2019

### How to tell what generation 4-channel module you have:

- 1<sup>st</sup> generation DW<sup>®</sup> Spot<sup>™</sup> 4-channel monitoring module's current firmware files start with: HS-10xx.
- 2<sup>nd</sup> generation DW<sup>®</sup> Spot<sup>™</sup> 4-channel monitoring module's current firmware files start with: FS-10xxC.

### New firmware notes:

1. Optimized the memory usage for the first generation 4-channel model (DW-HDSPOTMOD)
2. Fixed an auto login issue for first generation models with the previous firmware v1.3.4.5.
3. Updated the firmware version for second generation models to keep consistent with the first generation models.

### Firmware update notes

For 16-channel model (DW-HDSPOTMOD16), the firmware file updated to keep consistent with other firmware files.

### Firmware download info

[1<sup>st</sup> generation 4-channel DW-HDSPOTMOD](#)

[2<sup>nd</sup> generation 4-channel DW-HDSPOTMOD](#)

[16-channel DW-HDSPOTMOD16](#)

### For more information or technical support

DW technical support  
Toll free: 866.446.3595  
[digital-watchdog.com/contact-tech-support/](http://digital-watchdog.com/contact-tech-support/)

